

PROCESS SPECIFICATION

PROCESS SPECIFICATION NUMBER: ERA-1020

412 Auxiliary Fuel Tanks

FABRICATION AND INSTALLATION OF NON-STRUCTURAL COMPONENTS

PREPARED BY:

DAT

DATE: 6/12/87

John E. Stanley MESH PLASTICS LTD.

APPROVALS

			With their time that their time that their time that their time
MANUFACTURING	QUALITY CONTROL	ENGINEERING	
Leil W. Dukens	John E Its	Jan 1. E.	MESH
Joseph Flanner	Thurst & Thurs	Letugelly	ERA
	7		Miles and the second section of the section of the second section of the section of the second section of the



PROCESS SPECIFICATION

Scope: This specification outlines the requirements

for fabricating and installing the non-structural

components for the 412 Auxiliary Fuel Tanks.

Conformation:

This specification does not conform to any

existing government specification.

Subcontractors:

MESH PLASTICS, LTD. of Lake Charles, Louisiana,

or its subcontractor shall be the only subcontractors qualified to construct the FRP requirements and shall comply with this process specification. Any deviations or variations are to be submitted to ERA for approval with proper documentation prior to

fabrication.

Conflicts:

In the event of a conflict with engineering

drawing(s) and this specification, the

drawing(s) shall govern.

Fabrication and installation of the Non-Structural Components for the 412 Auxiliary Fuel Tanks

Rev. Date Pages Manufacturing Quality Control Engineering MESH ERA MESH ERA MESH ERA IR 6/12/87 ALL

PAGE 1 of 16

6/12/87

ERA	PS	1020	REV	IR	DATE	 6/12/87
ENA	ГО	TOLO:	II In V	TIV	DAIL	 0/12/0/

MATERIALS

MANUFACTURER MATERIAL NAME Derakane 8084 Midland, MI Resin Cobalt Napthenate AKZO Chemie Promoter New Brunswick, NJ Accelerator Dimethylaniline Buffalo Colors West Paterson, NJ Witco Chemical Hi Point 90 MEKP Catalyst Richmond, CA Lupersol DHD 9 Lucidol Chemical Buffalo, NY PVA Mold Release Rexco Carpenteria, CA Cerea Mold Release Wax Ceara Products, Inc. Denver, CO UV-9 UV Inhibitor Industrial Chemicals Atlanta, GA CoPlas Gel Coat CoPlas Inc. Ft. Smith, Ark. Spartan Pigment Spartan Pigment Co. Houston, Texas CoPlas CoPlas Inc. Ft. Smith, Ark.

PAGE 2 of 16

BY T. Harville PROCESS S REASON FOR CHANGE: ADD ALT P/N FOF	:PECIFIC	ATION	102	FECTED
REASON FOR CHANGE ADD ALT P/N FOR			EN LEVED ON	COMPUTER B
GLASS MAT (M127	R 3/4 & 1 ')	1/2		ATE: 'E''
3/4 oz TYPE "E" GLASS MAT.	M113-3/4 OR M127-3/4	oz C	/ICHITA FA	ALLS, TX. Ed
1 1/2 oz TYPE "E" GLASS MAT.	OR	1/2 0	z CERTA /ICHITA FA z CERTA /ICHITA FA	ALLS, TX AINTEED

(Amorphous Fumed Silica)

Putty filler

REV IR

DATE ____

6/12/87

MATERIALS

MATERIAL NAME

Aerosil

MANUFACTURER

Dequssa Corp. Teterboro, NJ

Cabosil

Cabot Corp. Boston, MA

Milled Fibers 731 ED

Owens-Corning Anderson, S.C.

3/4 oz Type 'E' glass mat M113 - 3/4 oz.

Certainteed

Wichita Falls, TX

1-1/2 oz Type 'E' glass mat Compatamat - 1-1/2 oz.

PPG Industries

Shelby, NC

M113 - 1 - 1/2 oz.

Certainteed

Wichita Falls, TX

10 mil 'C' glass, or

Modiglass

Reichold Chemical

Bremen, OH

Manville Glass

Manville Corp.

Denver, CO

10 mil 'A' glass veil

Surglass

Superior Glass

Bremen, OH

Kevlar Woven Roving

285 Kevlar F-100

Hexcel Corp. Chicago, Ill.

PAGE 3 of 16

ERA PS 1020 REV IR DATE 6/12/87

MATERIALS

MATERIAL

Paraffinated Styrene

TF-100

Industrial Chemicals Atlanta, GA

Grinding Discs

36 Grit Type D

60 Grit Type C

80 Grit Type C

80 Grit Type C

Mold surface Black Tooling Gel Glidden

PAGE 4 of 16

ERA	PS	1020	REV_	. IR	DATE_	6/12/87
-----	----	------	------	------	-------	---------

A. FABRICATION

- 1) Inspect molds for defects (ie. chips, cracks, crazing, etc. ...). DO Not proceed until any defect is corrected.
- 2) Apply mold release agent(s) according to manufacturer's instructions to molds.
- 3) Apply gel coat containing UV inhibitor onto mold using a spray gun to a nominal thickness of 10 mils.
- 4) Allow gel coat to cure for 4 6 hours until it is tack free.
- 5) Apply one layer of 3/4 oz type E glass mat on mold surfaces. Saturate with Derakane 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 6) Apply one layer of Kevlar woven roving over entire mold surface. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 7) Apply second layer of 3/4 oz type E glass mat on mold surfaces. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 8) Apply second layer of Kevlar woven roving over entire mold surface. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 9) Apply third layer of 3/4 oz type E glass mat on mold surfaces. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 10) Apply third layer of Kevlar woven roving over entire mold surface. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 11) Apply fourth layer of 3/4 oz type E glass mat on mold surfaces. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 12) Apply one layer of 10 mil veil over the entire mold surface. Saturate with 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 13) Separate part from mold and trim to size.

Page 5 of 16

ERA	PS	1020	REV	IR	•	DATE6/12/87	
							_

B. INSTALLATION

- 1) Confirm that part is trimmed properly by fitting into position.
- 2) Sand approxamately 3 inches all around outside edge of part and on tank shell where piece is to be attached.
- 3) Cut hole as required. Consult applicable drawing.
- 4) Attach part to tank using a minimal amount of putty. Allow to cure until putty hardens.
- 5) Apply one layer of 2" wide 1-1/2 oz. type E glass mat over putty with 1" extending onto the tank wall. Saturate with Derakane 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 6) Apply one layer of 3" wide 1-1/2 oz. type E glass mat over putty with 1-1/2" extending onto the tank wall. Saturate with Derakane 8084 resin containing UV inhibitor and pigment. Deaerate with serrated rollers.
- 7) Allow to cure for 4 hours.

Page 6 of 16

ERA	PS	1020	REV	IR	_ DATE _	6/12/87
-----	----	------	-----	----	----------	---------

INSPECTION

It is the purpose of the inspection to verify that each part has been fabricated in accordance with and meets the requirements of this specification.

RESPONSIBILITIES: It is the responsibility of the fabricator to make

available to ERA Helicopter or his authorized representative any or all of the following:

Records: Records pertaining to the part(s) being purchased

shall be supplied when requested. These may include:

Materials specifications

Equipment drawings or mold jig

Materials test results.

Dimensional verification reports.

Rework and repair reports.

MATERIALS:

Raw materials used for laminates shall be virgin materials and shall be free of contaminants as described in pgs. 11, 12, 13, 14, 15, and 16.

FABRICATED PARTS:

The part to be inspected shall be properly located and positioned, and shall be in condition to permit safe and thorough inspection. Reasonable means shall be provided to permit the inspector to visually examine the entire inner and outer surfaces of the part.

Allowable defects are listed on pgs. 9 and 10.

The following inspection tools and equipment shall be made available for use by the inspector.

Barcol hardness tester.
Acetone squeeze bottle with acetone.
Extension cord with ground fault switch.
A vapor tight inspection light.
Thickness gauge.

PAGE 7 of 16

ERA	PS	1020	REV	ĪR	DATE	6/12/87
-----	----	------	-----	----	------	---------

INSPECTION

TEST OF FINISHED PARTS:

The following basic tests shall be included as a minimum in the Acceptance Inspection.

Barcol Hardness Test - A test of resin cure shall be made in accordance with ASTM D2583. Take 10 readings, discard highest and lowest, average the remaining readings. Minimum acceptable average reading is 30.

Surface Cure Test - An acetone test shall be used to detect surface inhibition on surfaces exposed to air during cure. The procedure that shall be used is the following: rub a few drops of acetone on the surface and check for tackiness after the acetone has evaporated. Persistent tackiness indicates incomplete cure.

Dimensions - The inspector shall be provided with copies of all approved drawings or mold jigs.

OTHER APPLICABLE DOCUMENTS:

ASTM Standards

- C 581-74-Test Method for Chemical Resistance of Thermosetting Resins Used in Glass Fiber Reinforced Structures.
- D 638-77a-Test method for Tensile Properties of Plastics.
- D 790-71-Test Methods for Flexural Properties of Plastics and Electrical Insulating Materials.
- D 883-78a-Definitions of Terms Relating to Plastics.
- D 2583-75-Test Method for Identation Hardness of Rigid Plastics by Means of a Barcol Impressor.

PAGE 8 of 16

=	R	Δ	P	S	1020
С.	п	PA		~	1020

REV IR **DATE** 6/12/87

ALLOWABLE DEFECTS

Surface inspected Defect None Cracks(through part) Max dimension 1/2 in., max Crazing density 5 per sq. ft. min 2 (fine surface cracks) in apart Blisters(rounded elevations of the Max 1/4 in., dia x 1/8 in. laminate surface over high, max 1 per sq ft, min bubbles) 2 in apart Wrinkles and solid Max deviation, 20% of wall blisters thickness but not exceeding 1/8 in. Pits(craters in the Max dimensions, 1/6 in dia laminate surface) x 1/16 in deep, max density 10 per sq. ft. Max dimensions, 1/16 in dia Surface porosity(pinholes or pores in the x 1/16 in deep, max density 10 per sq. ft. laminate) Chips Max dimension of break, 1/4 in, and thickness no greater than 20 percent of wall thickness, max density 1 per sq ft Dry spot (nonwetted Max dimension, 2 sq in. per reinforcing) sq ft 1/8 in. max dia, 4 per sq Entrapped air (bubbles in. max density; 1/16 in. or voids in the laminate max dia. 10 per sq in. max density

PAGE 9 of 16

ERA PS _______1020 REV____ IR DATE ____ 6/12/87

ALLOWABLE DEFECTS

Surface inspected Defect

Exposed Glass None

Burned Areas None

Exposure of cut edges None

Max length 1 in. max depth Scratches

0.010 in.

1/16 in. dia., max density 1 Foreign Matter

per sq ft

ERA	PS	1020	REV	IR	DATE_	6/12/87
Pro 8 18 16 26				سان استنباره و محمد محمد و باز باز و باز	- Contract	

FIBERGLASS SURFACING MAT

1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize fiberglass surfacing mat used by the fabricator.

2.0 Definitions

- 2.1 Fiberglass Surfacing Mat A random arrangement of glass fibers bonded with a binder to form a thin porous mat which is supplied in roll form. Surfacing mat is usually used to reinforce the corrosion resistant resin rich liner on the inside of equipment and to provide a smooth surface on the exterior of equipment.
- 2.2 Binder Chemical treatment applied to the jackstraw arrangement of glass fibers to give the mat integrity. Specific binders are utilized to promote chemical compatibility with the various laminating resins used.
- 2.3 Slugs Unfiberized beads of glass.
- 3.0 Requirements
- 3.1 Visual Requirements Each roll of fiberglass surfacing mat shall be inspected to insure it is consistent in color, texture and appearance. Any holes, cuts or visual irregularities shall be removed from the mat prior to or during fabrication.
- 3.1.1 Slugs Mat which contains more than four slugs per 100 lineal feet is rejectable.
- 3.1.2 Wrinkles Crosswise wrinkles or waves that are visible at a 45 deg. angle and lengthwise wrinkles that can be readily flattened under pressure and that do not crease or change the dimensions of the mat are acceptable.
- 3.1.3 Wet Spots and Bar Marks The mat shall be free from these defects.
- 3.1.4 Delamination The mat shall not delaminate, i.e. shall not separate into layers in coming off the roll.

PAGE 11 of 16

ERA	PS	1020	REV_	1R	DATE	6/12/87
-----	----	------	------	----	------	---------

FIBERGLASS SURFACING MAT

- 3.2 Physical Properties
- 3.2.1 Thickness The thickness of the mat in each roll shall be measured.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the mat unusable.
- 3.3.1 The mat shall be packaged in an unbroken carton as shipped from the mat manufacturer's factory. The mat used shall not be repackaged in the distribution of the mat after the manufacturer has shipped the mat.
- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
 - * Visual inspection
 - * Width
 - * Thickness
 - * Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 12 of 16

ERA PS	S	1020	R	EV	IR	D A	T	E	6/12/87
--------	---	------	---	----	----	-----	---	---	---------

FIBERGLASS CHOPPED STRAND MAT

1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize fiberglass chopped strand mat used by the fabricator.

2.0 Definitions

2.1 Chopped Strand Mat - Chopped strand mat is made from randomly oriented glass strands which are held together in mat form using a binder. Each strand contains a sizing.

3.0 Requirements

- 3.1 Visual Requirements Each roll of chopped strand mat shall be inspected to insure it is consistent in color, texture and appearance. It shall be free from surface irregularities, fluffy masses, dirt spots or other foreign material; water spots, knots, binder spots larger than 2" in diameter, clumps of strands and tears of holes which may result form removal of defects.
- 3.2 Physical Requirements
- 3.2.1 Weight The square foot weight of the mat shall be measured for each carton of mat used. All specimens shall fall within the range specified for the product.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the mat unusable.
- 3.3.1 The mat shall be packaged in an unbroken carton as shipped from the mat manufacturer's factory. The mat used shall not be repackaged in the distribution of the mat after the manufacturer has shipped the mat.

PAGE 13 of 16

		1000	~ 1	40.107
DA	TE	· ·	6/	12/87

REV IR

ERA PS 1020

FIBERGLASS CHOPPED STRAND MAT

- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
 - * Visual inspection
 - * Width
 - * Thickness
 - * Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 14 of 16

ERA	PS	1020	REV	IR	DA	"	=	6/12/87
c n A			tt be W					

KEVLAR WOVEN ROVING

1.0 Scope

1.1 The scope of these procedures is to describe the visual, physical and mechanical parameters which characterize kevlar woven roving used by the fabricator.

2.0 Definitions

- 2.1 Kevlar Woven Roving Kevlar fiber rovings woven into a heavy weight fabric.
- 2.2 Wrap Ends The rovings which run in the longitudinal direction of the fabric, i.e., along the roll length of the fabric.
- 2.3 Fill Picks The rovings which run in the transverse direction of the fabric, i.e., across the roll length of the fabric.
- 2.4 Leno Strands A pair of warp ends at each edge of the woven fabric. One Leno warp end is always over each fill pick while the other Leno warp end is always under the fill pick. The Leno strands define the edges of the woven field and serve to stabilize the edges of the fabric.
- 3.0 Requirements
- 3.1 Visual Requirements
- 3.1.1 Dirt Spots Defined as all foreign matter, dirt, grease spots, etc. The average number of dirt spots (1/16" to 3/4" in diameter) per 100 lineal feet shall be 6 or less. All rolls shall be free of dirt spots in excess of 3/4" diameter.
- 3.1.2 Warp Ends All rolls shall be free of missing warp ends for more than two consecutive feet.
- 3.1.3 Fill Picks All rolls shall be free of consecutive missing picks in excess of five, or more than eleven missing picks, either individual picks or any combination of individual and multiple (2, 3, 4, or 5) picks, in any consecutive 100 lineal feet.
- 3.1.4 Fuzz Clumps and Loops The product is designed to exhibit proper laydown and shall be free of fuzz clumps or loops exceeding one inch in height from the surface.

PAGE 15 of 16

				•		# / 10 /OT
		4000		ΤÜ		6/12/8/
= P A	PS	1020	REV	IR	DATE	0,, 0.
II //\	. •		Al des V			

KEVLAR WOVEN ROVING

3.2 Physical Properties

- 3.2.1 Thickness The thickness of the mat in each roll of Kevlar shall be measured.
- 3.3 Packaging Requirement Packaging shall be visually inspected to assure proper labeling and that the package is free from damage that may render the ECDE glass unusable.
- 3.3.1 The Kevlar shall be packaged in an unbroken carton as shipped from the manufacturer's factory. The Kevlar used shall not be repackaged in the distribution of the Kevlar after the manufacturer has shipped the Kevlar.
- 3.4 Documentation It is the responsibility of the fabricator to maintain records showing the results of all material testing. This information shall show at a minimum, the following:
- (a) Form of material
- (b) Manufacturer
- (c) Manufacturer's product description including binder type (treatment)
- (d) Manufacturer's product code
- (e) Production date, if available, or production code on carton.
- (f) Property measured and value recorded
 - * Visual inspection
 - * Width
 - * Thickness
 - * Packaging
- (g) Job number (Internal Fabricator Control Number)
- (h) Fabricated part identification number

PAGE 16 of 16



Administration

MANUFACTURING INSPECTION DISTRICT OFFICE #43 SUITE 102A, 11503 JONES MALTSBERGER ROAD SAN ANTONIO, TEXAS 78216

June 30, 1987

Mr. David K. Murphy Chief Inspector ERA Helicopters, Inc. P.O. Box 6566 Lake Charles, Louisiana 70606

Dear Sir:

The following ERA Helicopters process specifications with associated FAA Form 8110-3 have been reviewed for quality control provisions and found acceptable:

ERA 1000 IR dated May 14, 1987
ERA 1000 "A" dated June 12, 1987
ERA 1016 IR dated April 17, 1987
ERA 1018 "A" dated May 11, 1987
ERA 1019 IR dated May 4, 1987
ERA 1020 IR dated June 12, 1987
ERA 1021 IR dated June 12, 1987
ERA 2002 IR dated March 9, 1987
ERA 4004 IR dated May 4, 1987
ERA 4006 IR dated April 17, 1987

The process specifications with associated FAA Form 8110-3 have been forward to FAA Engineering for post review.

Sincerely,

John F. Selgrath Acting Manager

John & Silgrath